

U. S. COAST GUARD LORAN-A TECHNICAL ASSISTANCE DETAIL, MANILA 3 FEB 76

P 030015Z FEB 76

FM COGARD LORTAD MANILA RP

TO COMCOGARD FESEC TOKYO JA

INFO JMSA TOKYO JA

CCGDFOURTEEN HONOLULU HI

BT

UNCLAS

LORSTA BATAN SYNCHRONIZATION PROBLEM

1. BOTH TMRS 2H4-S MALFUNCTIONED IN E-SYNC CONTROL AND 0-202 RESPECTIVELY.
2. PROBLEM CORRECTED 020030Z FEB 76.
3. REQ ADVISE THIS CMD IF FURTHER PROLONGED OFF SYNC PERSIST ON RATE 2H4-S.

BT

PRIORITY

030015Z FEB 76

J. G. JIMENEZ, CWO3, USCG

D. T. JONES, LT, USCG
COMMANDING OFFICER