

U. S. COAST GUARD LORAN-A TECHNICAL ASSISTANCE DETAIL, MANILA

MAY
4 MAY 76

R 040539Z MAY 76

FM COGARD LORTAD MANILA RP

TO CCGDFOURTEEN HONOLULU HI

BT

UNCLAS

TO ECV

1. OICCSWP CONTACTS WITH 1961 COMMS GP CLARK AB INDICATE MAJOR TOWER TEAM WORK MUST BE TASKED BY PACAF HICKAM. REQ CONTACT PACAF FOR FEASIBILITY.
2. SOURCE OF REPLACEMENT TOWER BATANES WAS NEVER BROUGHT UP IN OICC-COGARD DISCUSSIONS. 1961 CG HAS NO SUCH TOWER AVAILABLE. REQ ADVISE IF INTENTION IS TO OBTAIN REPL FM MFR OR HAVE BUILT LOCALLY.

BT

www.loran-history.info

ROUTINE

ROUTINE

R 040539Z MAY 76

D. T. JONES, LT, USCG

D. T. JONES, LT, USCG
COMMANDING OFFICER