## UNITED STATES COAST GUARD

ADDRESS REFLY TO

Commanding Officer LTS French Frigate Shoals Box 4010, Honolulu, T.H.





31 August 1951 A9-8

.From: LTJG E.L. HAUFF, USCG (4083)

To: COMMANDANT

Via: (1) Commanding Officer, LTS French Frigate Shoals

(2) Commander, 14th Coast Guard District

Subj: USCGLTS French Frigate Shoals; relief of command of

Ref: (a) Article 7-1-25, Coast Guard Regulations

(b) Ind-12 to SMEETGUM letter 4-7-51, P16-4/00, order no. 511183

- 1. In accordance with reference (b), LTJG Norman P. Ensrud, USCG reported to this command at 0830, 16 August 1951, and the following action was taken, in compliance with reference (a), to relieve the command:
  - (a) An inspection of the unit was made by me in company with my relief and the defects and peculiarities of the station were pointed out.
  - (b) The personnel were exercised at fire drill in the presence of my relief and myself.
    - (c) All regulations and orders in force, and all official correspondence and information concerning the unit and personnel thereof, were delivered to my relief together with all documents required to be kept or supervised by the Commanding Officer.
    - (d) The narcotics, armament, station keys, and combination to the lock-file cabinet were delivered to the relieving officer.
    - (e) A transfer-of-command inventory report of all registered publications charged to this unit was executed with my relief, in accordance with current communications instructions.
    - (f) The Commuted Ration Mess was found to be in satisfactory condition at the time of relief.
- 2. With the crew at muster, orders of detachment were read by me and the command of the unit turned over to LTJG Norman P. Ensrud, USCG who then read his orders and assumed command at 1315 this date.

EL Vaux

Amazaran, Amazaran,

31 angueb 1951 L-bni

af on average 1951

Fromt Commanding Officer, CGLTS French Frigate Shouls

To: Commandant

Via: Commander, 14th Coast Guard District

The conditions as set forth in the basic letter were found to be

Vie: (1) Commanding Chicor, LTS French Triggte Shoels

Regular maintenance has been carried out on the buildings but due to the temporary nature of the buildings the general condition is poor. The main floor beams in most of the buts were body rusted through. The half purlies or stringers which support the sheeting were also budly rusted. The sheeting although recently repaired is still in need of repair. The arch ribs which are in exposed areas were rusted. Screens and doors are in poor condition. The fresh mater senitary system was badly corrected in several exposed places. Many of the buildings have eaged and/or twisted due to the elements.

3. There was only one distiller unit on the station.

h. Meither the engine in the motor self bailer nor the outboard motor for the 20 foot dingly were in operating condition. Spare parts have been oredered.

5. conclus main dorain translatting alterna aground system has been uncovered in several places by birds and turtles which are integrated on the island. This condition has led to possible displacement and breakage of the ground system in a condition has led to possible displacement and breakage of the ground system in a condition of the ground system in a condition of the condi

personnel thereof, were delivired to by boton as boton all.6 decumpation of the Commending decumpation. Consending of the Consending

(d) The narcotice, arement, station legs, and combination to the lock-file cabinet were delivered to the relieving criter.

(a) A transfer-of-command inventory report of Market reliable.

publications charged to this unit was executed with the reliad.

In accordance with current communications incorrectly.

(1). The Commuted Dation Mass was found to be in mating of the condition at the time of relief.

Slip

Ind-2

AIR MAIL p 17 September, 1951 A9-8

Commander, 14th CG District Commandant (OSU)

To:

Subj: CGLTS French Frigate Shoals; relief of command of

Forwarded approved.

Chief of Staff

U. S. COAST CUARD

SEP 24 1951

LICAS-STILL LITTS .