



DEPARTMENT OF TRANSPORTATION
UNITED STATES COAST GUARD

RECEIVED

SEP 11 1974

MAILING ADDRESS:

Commanding Officer
USCG Base, Box 14
FPO Seattle 98790

5522

5 September 1974

CHIEF, OPERATIONS DIVISION
17th COAST GUARD DISTRICT

From: Commanding Officer, USCG Base Kodiak, Alaska
To: Commander, Seventeenth Coast Guard District (o)
Subj: Inspection of Spruce Cape Loran Station; result of
Ref: (a) Article E-11-6, CCGD17 OPLAN 1-(YR)

1. An inspection of subject was held 28 August 1974. Inspection conducted by CAPT W. E. WEST.
2. Upon arrival, a Personnel Inspection was held and is rated "Excellent". No discrepancies noted.
3. The Supply and Administrative procedures are being maintained in accordance with current directives. Personnel and Health records are held by Base Kodiak.
4. The proper Commissary procedures are being adhered to in that stock cards, proper break-out slips, and inventories are current and up-to-date. The galley area and reefer spaces are clean and well maintained.
5. The Armory is clean and weapons are properly stowed.
6. Berthing areas are clean and orderly.
 - a. Shower deck needs refinishing.
7. Engineering spaces and equipment therein are clean and properly maintained.
 - a. Sewage Treatment Plant is operating efficiently and effluent is properly chlorinated.
 - b. One fifty pound CO₂ bottle located in the Transmit room did not have an inspection tag. (Needs charging and a hydrostatic test).
 - c. New garage door needed. Present door beyond economical repair.
 - d. Interior of garage needs painting (Staging to be furnished by Base Kodiak, Public Works Division).

Obj: Inspection of Spruce Cape Loran Station; result of

- e. First Aid Kit in Transmit room needs restocking.
- 8. There is no evidence of pest problems. Sanitation is very good.
 - a. Weed killer improperly stowed in the lofts. (Moved to a metal locker).
- 9. The trash dumpster is in need of repair. Base Kodiak, Public Works Division will provide a new dumpster.
- 10. In conclusion, the Station equipment and spaces reflect proper maintenance and care by the personnel assigned.

W. E. West
 W. E. WEST

Copy to:
LORSTA Spruce Cape

- 4. The proper commissary procedures are being followed to insure that stock cards, proper bills and slips, and inventories are current and up-to-date. The storage areas and transfer spaces are cleaned and well maintained.
- 5. The Armory is clean and weapons are properly stored.
- 6. Berthing areas are clean and orderly.
 - a. Shower stalls need refinishing.
- 7. Engineering spaces and equipment therein are clean and properly maintained.
 - a. Sewage Treatment Plant is operating efficiently and effluent properly characterized.
 - b. The fifty pound CO₂ bottle located in the Transmit room did not have an inspection tag. (Needs charging and hydrostatic test).
 - c. New garage door needed. Present door beyond economical repair.
 - d. Interior of garage needs painting (staging to be furnished by Base Kodiak, Public Works Division).